Water System	Date	EPA Method	VOC	SOC	NO <sub>3</sub> (mg/l)	Cl (mg/l)	Electrical Conductivity
206 Olympia St Parking Lot	08/02/95		ND				
4th & WA Fountain	11/28/88		ND				
4th & WA Fountain	04/21/92	524.2	ND				
4th & WA Fountain	08/03/95		ND				
4th & WA Fountain	08/02/05				0.057	1.94	
Bigelow Springs Park	08/15/95		ND				
Diamond Parking	11/28/88	524.0	ND				
Diamond Parking	04/21/92		ND				
Diamond Parking	05/10/93	524.2	ND				
Diamond Parking	08/01/95	515.1	ND				
Diamond Parking	08/03/95		ND				
Diamond Parking	11/12/96	Various	ND		< 0.1	6	
Diamond Parking	11/17/98		ND		< 0.5	1.8	150
Diamond Parking	04/06/00				< 0.2		
Diamond Parking	04/24/01				< 0.2		
Diamond Parking	04/01/02				< 0.2		
Diamond Parking	04/01/03				< 0.2		
Diamond Parking	04/13/04				< 0.1		
Diamond Parking	???				0.01	2.73	
King Solomon's Reef	06/30/80				0.5		
King Solomon's Reef	04/21/92		ND				
King Solomon's Reef	01/13/94				0.4		
King Solomon's Reef	01/26/97		ND	ND	0.2	2	130
King Solomon's Reef	02/04/98				0.2		
King Solomon's Reef	09/04/02				0.3		
King Solomon's Reef	12/08/03				0.2		
Spar Restaurant	08/31/83				< 0.2	5	170
Spar Restaurant	02/18/87				< 0.2	7	215
Spar Restaurant	11/28/88	524.0	ND				
Spar Restaurant	04/21/92	524.2	ND				
Spar Restaurant	01/13/94				< 0.2	2	161
Spar Restaurant	01/26/97		ND	ND	< 0.2		
Spar Restaurant	01/27/98				< 0.2		
Spar Restaurant	03/25/99				< 0.2		
Spar Restaurant	07/27/00				< 0.2		
Spar Restaurant	01/18/01			`			
Spar Restaurant	07/12/01				< 0.2		
Spar Restaurant	09/05/02				< 0.2	3	163
Spar Restaurant	12/29/03				< 0.2		
Carea Destassant	06/17/04				0.0		

## Table 1. Groundwater Quality Results for the Tumwater Sand Aquifer.

< 0.2

06/17/04

Spar Restaurant